

Alert number **[0467/05](#)**



Notifying country **Slovakia**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Toy set - MILITARY MEN SOLDIER FORCE including a machine rifle, knife in a case, truncheon, police emblem, target in the form of a figure, 2 grenades and 5 projectiles with suction cups (model N° 300)**

Risk type **Suffocation**

Risk description **Risk of suffocation. The projectiles with suction cups are not sufficiently long to be removed from a child's throat, in the event that they block the air passages. The relevant requirements of the European standard with regard to size were not complied with.**

Country of origin **People's Republic of China**

Measures taken by economic operators **Other : Voluntary withdrawal from sale. Sale banned by the authority that ordered the retailers to inform consumers about the possibility of returning the goods.
Other**

Alert number

0466/05



Notifying country **Slovakia**

Product category **Other**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Plastic eraser of various fruit shapes in pastel colours**

Risk type **Suffocation**

Risk description **Risk of suffocation. The product can be mistaken for sweets. Due to the shape, colour and appearance of the erasers, there is a risk that small children can mistake them for foodstuffs. After being placed in the mouth, the product can be swallowed or breathed in and thus put health at risk.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Sale banned by the authority that ordered the retailers to inform consumers about the possibility of returning the goods.
Other**

Alert number **0465/05**

Notifying country **Greece**

Product category **Motor vehicles**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Motor vehicle - Car "Suzuki Ignis" 1.5 (RG415)(model with engine type M15, cubic capacity of 1.5 litres and frames from JSAFHV81S00100188 to JSAFHV81S00105149 and production dates from 01.08.2003 to 09.01.2004)**

Risk type **Injuries**

Risk description **The LH drive shaft may disconnect from transmission due to the improper design with insufficient drive shaft holding to transmission by drive shaft circlip. Vehicle use under the high-speed driving condition can reduce the connecting force of drive shaft from transmission, causing revolution of the drive shaft. Such a condition can disconnect drive shaft from transmission and the vehicle can be unable to be driven.**

Country of origin **Japan**

Measures ordered by public authorities **Other : The importer has informed the owners through individual letters in order for them to visit the network of authorised Suzuki repairs for replacement of the defective part.
Other**

Measures taken by economic operators **Other : The importer has informed the owners through individual letters in order for them to visit the network of authorised Suzuki repairs for replacement of the defective part.
Other**

Alert number **0464/05**



Notifying country	Czechia
Product category	Lighting equipment
Type	Consumer
Product	&nbsp;
Brand	Unknown
Product description	Bathroom electrical stationary luminaries “SIEPER”(model: Type 5425/1, model CHICO GL)
Risk type	Electric shock Fire
Risk description	The instructions for use are incorrect and if follow they jeopardize the safety. Insufficient resistance to flame and ignition.
Country of origin	Germany
Measures ordered by public authorities	Other : Sales ban and ban on placing on the market ordered by the authority. Other

Alert number

0463/05



Notifying country **Finland**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Balloon powered toy car "JET RACER"(model CL-600)**

Risk type **Choking**

Risk description **Risk of choking. The toy contains a separate, loosely attached balloon nozzle. The toy does not fulfil the relevant requirements for mouthpieces attached to balloons. One accident happened in Finland where an 8-year old child accidentally inhaled the mouthpiece while blowing up the balloon and nearly choked to death.**

Country of origin **People's Republic of China**

Measures taken by economic operators **Other : Voluntary recall of products from the consumers and withdrawal from the market.
Other**

Alert number **0462/05**

Notifying country **Germany**

Product category **Motor vehicles**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Motor vehicle accessories - Rear-mounted cycle rack "Uebler" for Mercedes Benz Class A (model: B6 684 8282)**

Risk type **Injuries**

Risk description **Risk of injury. Bicycles can become detached from the rack and fall on the road.**

Country of origin **Germany**

Measures ordered by public authorities **Other : Voluntary recall of the racks concerned via the Mercedes-Benz branches for checking and replacement if necessary. The authority is still to take a decision on whether compulsory measures are necessary on German territory.
Other**

Measures taken by economic operators **Other : Voluntary recall of the racks concerned via the Mercedes-Benz branches for checking and replacement if necessary. The authority is still to take a decision on whether compulsory measures are necessary on German territory.
Other**

Alert number **0461/05**

Notifying country **Portugal**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Toy set of police equipment “City Police Set”(model 1015486)**

Risk type **Injuries
Suffocation**

Risk description **Risk of injury and suffocation. The suction-tip separated from the projectile during the traction test, presenting two separate risks: because there is no any protection (suction-tip) at the end of the rigid projectile, it can be shot without any impact-cushioning surface, and could cause injuries if shot at a person; if accidentally swallowed, the suction-tip detached from the projectile could cause suffocation of the child if it lodges in the throat and blocks the airway, it being difficult to remove because it is difficult to obtain a firm hold.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : The competent authority has ordered the person responsible for placing the product on the market to stop marketing the product.
Other**

Alert number

0460/05



Notifying country **Spain**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Toy bow and arrows "SUPER" covered by elastic suction cups (model 328)**

Risk type **Injuries
Suffocation**

Risk description **Risk of suffocation/injury. Elastic suction cups can easily come off, can be ingested by small children and lodge and block the air passages and cause suffocation. Arrows without protective suction cups can cause injuries. Toy does not comply with the relevant European standards for traction (to remove suction cups) and kinetic energy of arrows.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Products withdrawn from the market/distribution chain by authorities.
Other**

Alert number **0459/05**



Notifying country **Hungary**

Product category **Electrical appliances and equipment**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Electrical earthed T-connector “Dealer”(model 40288/20241)**

Risk type **Electric shock**

Risk description **Risk of electric shock. There are deficiencies in the connector dimensions, fixing of internal earthing parts can come apart during use thereby exposing live components**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Products withdrawn from the market/distribution chain by authorities.
Other**

Alert number

0458/05



Notifying country **Czechia**

Product category **Childcare articles and children's equipment**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Childcare PVC feeding bottle with teat and brush "VIDAL EUROPE 0794722 BIBERON 2 PZAS"**

Risk type **Chemical**

Risk description **Teat contains mixtures of two banned phthalates (3,2% w/w DBP, 4.6 % w/w DEHP) from use in PVC toys and childcare articles intended to be put in the mouth of small children. Product also contains 17.1% w/w of another phthalate (DIBP).**

Country of origin **Unknown**

Measures ordered by public authorities **Other : Products seized and withdrawn from the market/distribution chain by authorities. Product recall from consumers. Warnings issued by authorities. Other**

Alert number **0457/05**

Notifying country **Greece**

Product category **Other**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Luminous lollipop with batteries “Nite Pop” with plastic handle with a battery button (on/off) and wrapped with coloured label ((Ref. NP 001)**

Risk type **Suffocation**

Risk description **Risk of suffocation. Plastic cover and plastic handle containing the button size batteries can easily be detached (fails the relevant European standard) and the button size batteries can be swallowed by small children and block their pharynx thus leading to suffocation (size of batteries fails requirements of European standards). No CE marking.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Products seized and withdrawn from the market/distribution chain by authorities.
Other**

Alert number

0456/05



Notifying country **Germany**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Plastic/rubber snake (toy)Country impressed on the product, no relevant documentation.**

Risk type **Chemical
Injuries**

Risk description **Parts of the snake can be easily detached, be swallowed by small children. Upon swallowing they can harden and lodge in the digestive track. In addition, presence of phthalate plasticisers (DEHP 40.3% and DINP 1.5% banned under national provisions were identified.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : No remaining stocks, no tracing of distribution list. Authorities in search of distribution channels for eventual removal from the market.
Other**

Alert number **0455/05**

Notifying country **Poland**

Product category **Motor vehicles**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Motor vehicle - Car "Renault Clio 2" produced from 08.05.03 to 18.11.04**

Risk type **Injuries**

Risk description **Risk of injury. Risk of short circuit in the loom of the horn placed in the steering wheel and touches the module of the air bag can result in the malfunctioning of all three components.**

Country of origin **Czechia**

Measures taken by economic operators **Other : Voluntary measures by importer to inform dealers and via them individual customers to bring in vehicles for free of charge repairs.
Other**

Alert number **0454/05**

Notifying country **Poland**

Product category **Motor vehicles**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Motor vehicle - Car “Renault Modus” produced until 05.04.05**

Risk type **Injuries**

Risk description **Risk of injury. Improper settling in of crankshaft of steering column can influence the stability of the driving/steering function.**

Country of origin **Unknown**

Measures taken by economic operators **Other : Voluntary measures by importer to inform dealers and via them individual customers to bring in vehicles for free of charge repairs.
Other**