

Alert number 0715/05



Notifying country Hungary

Product category Lighting chains

Type Consumer

Product

Brand Unknown

Product description Lighting chain "Everstar" Type/model: G-100/4F.

Risk type Electric shock

Risk description There is a single-core, single insulated flexible wire applied between the lamps insulated by a single shrink tube, soldered into the cable and the flashing unit that may cause electric shock. The inlet of the flashing unit is not rounded, the cord anchorage is missing and the plug is not standardized. This product does not comply with the LVD Directive and the European Standards.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Withdrawal from the market and prohibition of distribution ordered by the authorities.
Other

Alert number

0714/05



Notifying country

Greece

Product category

Electrical appliances and equipment

Type

Consumer

Product

Brand

Unknown

Product description

Cordless kettle "Best" for household use.Type/model: HEK-8009.

Risk type

Electric shock

Risk description

The conductors of the supply cord have nominal cross sectional area 0,75mm², whereas the less permitted cross sectional area is 1mm².The withholding hook of the sample does not protect the conductors from twisting. The withholding hook of the supply cord is not sufficient. The length of the earth conductor is such that it does not ensure that the earth conductor will disconnect after the disconnection of the live conductors, in case the supply cord gets out of the withholding hook. The screws inside the insulating material of the sample cause damage to the insulating material This product does not comply with the LVD Directive and the European Standard.

Country of origin

People's Republic of China

Measures ordered by public

Other : Withdrawal from the market ordered by the authority.

authorities Other



Alert number 0713/05



Notifying country Hungary

Product category Lighting chains

Type Consumer

Product

Brand Unknown

Product description Lighting chain "Everstar" Type/model: G-60/2F.

Risk type Electric shock

Risk description There is a single-core, single insulated flexible wire applied between the lamps insulated by a single shrink tube, soldered into the cable and the flashing unit that may cause electric shock. The inlet of the flashing unit is not rounded, thus the cable may get damaged, the cord anchorage is missing and the plug is not standardized. This product does not comply with the LVD Directive and the European Standards.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Withdrawal from the market and prohibition of distribution ordered by the authorities.
Other

Alert number 0712/05



Notifying country Hungary

Product category Lighting chains

Type Consumer

Product

Brand Unknown

Product description Lighting chain "Everstar" Type/model: G-240.

Risk type Electric shock

Risk description There is a single-core, single insulated flexible wire applied between the lamps insulated by a single shrink tube soldered into the cable and the flashing unit that may cause electric shock. The inlet of the flashing unit is not rounded, thus the cable may get damaged, the cord anchorage is missing and the plug is not standardized. This product does not comply with the LVD Directive and the European Standards.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Withdrawal from the market and prohibition of distribution ordered by the authorities.
Other

Alert number 0711/05



Notifying country	United Kingdom
Product category	Toys
Type	Consumer
Product	
Brand	Unknown
Product description	Puffer Ball (toy).Type/model: Unknown. Description: Round balls with tendrils, 11cm & 15cm, in yellow, green, red, blue, orange, purple (but without flashing lights or liquid inside). Strong petroleum base smell type.
Risk type	Fire
Risk description	The smallest flame/mildest contact with flame and tendrils burn violently and the fire spreads rapidly. It was considered that the polymer material used for the Puffer Balls was highly flammable. Toy does not comply with the Toys Directive and the European Standards.
Country of origin	People's Republic of China
Measures taken by economic operators	Other : Distribution of the product voluntarily stopped by the importer. Recall letters and notices were sent to the retailers. Other

Alert number 0710/05



Notifying country Hungary

Product category Lighting equipment

Type Consumer

Product

Brand Unknown

Product description Portable desk lamp "Fillip" Type/model: L-VALS.

Risk type Electric shock
Injuries

Risk description At the cable inlet of the switch the single insulated wires are accessible, and may cause electric shock. There are burring metal screws protruding from the metal frame supporting the lamp holder. This product does not comply with the LVD Directive and the European Standards.

Country of origin Romania

Measures ordered by public authorities Other : Withdrawal from the market and prohibition of distribution ordered by the authorities.
Other

Alert number 0709/05



Notifying country Hungary

Product category Lighting equipment

Type Consumer

Product

Brand Unknown

Product description Portable desk lamp "Fillip" Type/model: L-MENUETT

Risk type Electric shock
Injuries

Risk description Sharp and burring screws and plates protrude from the luminaire (risk of injury). The mains cable is led along sharp glass edges and through threaded, burring metal bushing to the contacts of the lamp holder. When moving the luminaire the insulation of the wire may get damaged thus there is a risk of electric shock. This product does not comply with the LVD Directive and the European Standards.

Country of origin Hungary

Measures ordered by public authorities Other : Withdrawal from the market and prohibition of distribution ordered by the authorities.
Other

Alert number 0708/05

Notifying country Greece

Product category Motor vehicles

Type Consumer

Product

Brand Unknown

Product description Scooter "SUZUKI" Type/model: AN 650 AK5.

Risk type Fire

Risk description Inadequate adaptation of the fuel pump retainer, resulting in fuel leak under certain conditions (expansion or contraction of the fuel tank).

Country of origin Japan

Measures taken by economic operators Other : Voluntary corrective actions.
Other

Alert number 0707/05



Notifying country Czechia

Product category Lighting equipment

Type Consumer

Product

Brand Unknown

Product description Wall/ceiling mounted fixed luminaire "TOP LIGHT"
Type/model: 5501/40, model 85-3703/21.

Risk type Electric shock
Fire

Risk description Risks caused by overheating of internal wires and overheating of terminal blocks. This product does not comply with the LVD Directive and the European Standards.

Country of origin Unknown

Measures ordered by public authorities Other : Prohibition of distribution ordered by the authority.
Other

Alert number 0706/05



Notifying country	Greece
Product category	Motor vehicles
Type	Consumer
Product	
Brand	Unknown
Product description	Scooter KYMCOType/model: XCITING 500, (serial numbers: RFBT7000051600101~ RFBT7000051600604).
Risk type	Injuries
Risk description	Rider's safety risk due to damage of the engine. Precautionary replacement of the chain tentioner. It can cause noise and in some specific cases damage of the engine.
Country of origin	Taiwan
Measures taken by economic operators	Other : Voluntary corrective actions and consumer information. Other

Alert number 0705/05



Notifying country Hungary

Product category Hobby/sports equipment

Type Consumer

Product

Brand Unknown

Product description Plastic gun with laser pointer (in the scale of 1/1- light industrial product).Brand: Both elephant.Type/model: No. 928A (no EAN code).

Risk type Injuries

Risk description Considering the material and construction of the product it can be confused with a toy gun, and therefore can be attractive for children. The intended age group (above 14 years) is indicated only in English. There were no instructions for use on the safe use attached to the product in Hungarian. The graphic symbol is misleading. A kinetic energy of the missile is higher than allowed (see attached test report), and taking into account the foreseeable use by children this may imply a risk of injury.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Prohibition of distribution by the authority.
Other

Alert number 0704/05



Notifying country Hungary

Product category Hobby/sports equipment

Type Consumer

Product

Brand 1. Air Sport Gun, 2. Flashlight,3. Power Sport Gun CH-0881A2, 4. Power Sport Gun CH-0181A,5. Military Force.

Product description Plastic guns. Brand: 1. Air Sport Gun, 2. Flashlight,3. Power Sport Gun CH-0881A2, 4. Power Sport Gun CH-0181A,5. Military Force.Name: Plastic guns.Type/model: 1. CQ. P89A,2. P191C, 3. CH-0881A2, 4. CH-0181A,5. P 625 B.

Risk type Injuries

Risk description A kinetic energy of the bullet is higher than allowed and taking into account the foreseeable use by children this may imply a risk of injury. Considering the material and construction of the products they can be confused with a toy guns, and therefore can be attractive for children. However the intended age group (Sample 1, 3 and 4: above 18 years; Sample 2 and 5: above 14 years) is indicated only in English. There were no instructions for use attached to the product in Hungarian.

Country of origin People's Republic of China

Measures ordered by public Other : Distribution of the product prohibited by the

authorities

authorities. Recall from the consumers ordered by the
authority.
Other

Alert number 0703/05



Notifying country Germany

Product category Electrical appliances and equipment

Type Consumer

Product

Brand Unknown

Product description Electric hand-held mixer "Philips - Küchenmixer"Type/model:Cucina HR 1560, 1561, 1565; Serial number 04420 to 05170; 200 000 mixers that are faulty and were manufactured between October 2004 and April 2005.

Risk type Injuries

Risk description By unintentional pressing of the separate "Turbo button", which is easily activated, the equipment starts up at 100% power. If this happens during the changing or insertion/removal of the kneader attachment or the whisk attachment there is a risk of serious injury to the hands. Accident, during the changing /insertion or removal of the kneader attachment or the whisk attachment one consumer almost lost a thumb.

Country of origin Czechia

Measures ordered by public authorities Other : Publishing of a warning and offer to exchange by the manufacturer.
Other

Measures taken by
economic operators

Other : Publishing of a warning and offer to exchange by the
manufacturer.
Other

Alert number 0702/05

Notifying country Ireland

Product category Motor vehicles

Type Consumer

Product

Brand Unknown

Product description Luxury 4 wheel drive vehicle "Nissan"Type/model: R51 Pathfinder.

Risk type Injuries

Risk description A number of vehicles may not have the correct torque applied to the bolts in the propeller shaft during production. Propeller shaft bolts require that the torque setting be checked and set to specification. Bolts may need to be replaced if required. If loose bolts are not attended to, the propeller shaft could possibly become detached from the vehicle.

Country of origin Spain

Measures taken by economic operators Other : Voluntary corrective actions in Europe.
Other