

Alert number 0178/07



Notifying country Bulgaria

Product category Lighters

Type Consumer

Product Novelty lighters

Brand Unknown

Type / number of model Unknown


Risk type Burns
Fire

Risk description This product poses a risk of burns and fire in particular to children because it bears a resemblance to other products and it may be attractive to children (entertainment functions are included). This product does not comply with the relevant European standard EN 13869.

Country of origin Unknown

Measures ordered by public authorities Other : Sales ban and information to consumers ordered by the authorities
Other

Alert number 0177/07



Notifying country	Slovakia
Product category	Electrical appliances and equipment
Type	Consumer
Product	Cord extension set with over voltage protection
Brand	JONEX
Type / number of model	Type: PS-5P/5m
Risk type	Electric shock Fire
Risk description	This product poses a risk of electric shock and fire. It does not comply with the relevant standard with respect to: - length of protective conductor; - safety-fuses in network T 10A (current carrying capacity is 16A); - heating of supply conductors; - unsuitable type of cord.
Country of origin	Poland
Measures taken by economic operators	Other : Voluntary stop of sales, information to consumers and recall of the product taken by the distributor Other

Alert number 0176/07



Notifying country Bulgaria

Product category Toys

Type Consumer

Product Children watches

Brand Lefeng

Type / number of model Unknown

Risk type Choking

Risk description This product poses a risk of choking to children because the small batteries are accessible for children without the use of instrument (lid of the battery compartment opens with one movement). This product does not comply with the relevant European standard EN 50088.

Country of origin Unknown

Measures ordered by public authorities Other : Sales ban and information to consumers ordered by the authorities
Other

Alert number 0175/07

Notifying country Greece

Product category Motor vehicles

Type Consumer

Product Motorcycle

Brand YAMAHA

EC-type approval/model Motorcycles, model YZF MT 03 '06. The recall concerns 2006 model year YAMAHA YZF MT 03 '06 motorcycles.

Risk type Injuries

Risk description In affected motorcycles, high-pressure washing or long usage in rainy conditions can cause water infiltration inside the main wiring harness' protection. This water could remain for a long time inside the wiring harness area, which is U-shaped and trickle down into the TPS wire through a joint. This could cause a corrosion problem, especially inside the TPS coupler. As a consequence, the TPS signal could be disturbed causing incorrect ignition advance and injection timing to occur, with one or more of the following symptoms: - engine difficult to start; - bad engine response; or - muffler overheating that may cause certain plastic parts to melt and/or muffler damage. These symptoms (especially the second one) could lead to loss of control of the motorcycle. Moreover, this product poses a serious risk of injuries because breakage of the side stand bracket may occur when the product is placed on its stand and the stand is then used as a pivot and during transport. No breakages have occurred whilst the product has been ridden. The breakage is caused by stress concentration due to bracket shape and its fixing structure. Breakage of the side stand bracket could cause side-fall of the motorcycle, resulting in possible injury of the rider. During transportation on a trailer/van/truck, an accident is possible due to instability of the machine after breakage.

Country of origin Italy

Measures taken by
economic operators

Other : Voluntary corrective actions taken by the importer
Other

Alert number 0174/07



Notifying country Hungary

Product category Clothing, textiles and fashion items

Type Consumer

Product Polar baby clothing set

Brand Happy bears

Type / number of model 6 Ha H.L.-O (bar code: 7000037135730)

Risk type Suffocation

Risk description This product poses a serious risk of suffocation because it has the pulling cord and the plastic end-piece in the hood. These elements are not allowed in baby clothing. This product does not comply with the relevant European standard EN 14682.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Withdrawal from the market and recall from consumers ordered by the authorities
Other

Alert number 0173/07



Notifying country Spain

Product category Toys

Type Consumer

Product Metal bucket - 'The Triplets' bucket gift set

Brand Unknown

Type / number of model Bar code: 8410399228756

Risk type Cuts

Risk description This product poses a risk of cuts because the edges of the bucket's handle are sharp. Incident reported: one child suffered injuries to the neck. The toiletries contained inside the bucket were not subject to the laboratory tests. This product does not comply with the relevant European standard EN 71.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Withdrawal from the market ordered by the authorities
Other

Alert number 0172/07



Notifying country Czechia

Product category Childcare articles and children's equipment

Type Consumer

Product Wheeled child conveyance

Brand Style AT + set M 655

Type / number of model Type 9932 BÉBÉ Car, model 2006, EAN 5602385264050

Risk type Chemical Injuries

Risk description The product poses a serious risk of injuries (breaking, dislocation or contusion) because there are openings in the access zone where the fingers of a child could be entrapped. Sharp edges and tips were also detected, posing a risk of cuts. In addition, the product poses a chemical risk due to the high value of DEHP phthalate present. This product does not comply with the relevant European standard EN 1888.

Country of origin Portugal

Measures ordered by public authorities Other : Sales ban ordered by the authorities
Other

Alert number 0171/07



Notifying country Czechia

Product category Childcare articles and children's equipment

Type Consumer

Product Sport wheeled child conveyance

Brand TechRider S

Type / number of model Ping Pong

Risk type Injuries

Risk description This product poses a serious risk of injuries (crash/jam/break of fingers) because there are openings in the access zone where the fingers of a child could be entrapped. This product does not comply with the relevant European standard EN 1888.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Sales ban ordered by the authorities
Other

Alert number 0170/07



Notifying country Spain

Product category Motor vehicles

Type Consumer

Product Mini motorbike – Minimoto pocket bike GP 49.9 CC Carenada

Brand Unknown

EC-type approval/model Snuggers KT-28

Risk type
Cuts
Fire
Injuries

Risk description This product poses a serious risk of injuries, fire and cuts because: - sharp edges are located close to the foot representing a driving hazard; - moving elements (chain) have no protection to avoid body parts becoming trapped when the product is in operation and to avoid foreign bodies like stones or other objects interfering with its correct operation; - fingers can get trapped interfering with the normal handling of the drive and control devices which can cause accidents; - the petrol pipe is not made of rigid material but of very weak, flexible rubber, which risks cracking in use due to overheating because it is in contact with the exhaust pipe. This results in a risk of explosion because it is located just above the engine. The product does not comply with the Machinery Directive.

Country of origin People's Republic of China

Measures ordered by public
authorities

Other : Withdrawal from the market ordered by the authorities
Other

Alert number 0169/07



Notifying country Czechia

Product category Childcare articles and children's equipment

Type Consumer

Product Wheeled child conveyance

Brand Neonato

Type / number of model type N 755, model Matteo, supplied as Speedy C 820/ EAN 8 005549728202

Risk type Injuries

Risk description This product poses a serious risk of injuries (crash/jam/break of fingers) because there are openings in the access zone where the fingers of a child could be entrapped. During tests of the locking device of the folding mechanism, the pushchair also collapsed. In addition, the instructions for use are not in Czech. This product does not comply with the relevant European standard EN 1888.

Country of origin Italy

Measures ordered by public authorities Other : Sales ban ordered by the authorities
Other

Alert number	<u>0168/07</u>
Notifying country	Greece
Product category	Motor vehicles
Type	Consumer
Product	Passenger car - Renault R21
Brand	RENAULT
EC-type approval/model	model R21 Turbo. The recall concerns vehicles produced from 1 January 1987 to 31 May 1993.
Risk type	Fire
Risk description	This product poses a serious risk of fire because due to immobilising fault, a loosening of the turbocharger oil supply pipe is possible. Presence of oil on the hot surface of the turbocharger can cause a serious risk of fire.
Country of origin	France
Measures taken by economic operators	Other : Voluntary corrective measures taken by the importer Other

Alert number	<u>0167/07</u>
Notifying country	Norway
Product category	Machinery
Type	Consumer
Product	Cordless reciprocating saw
Brand	Dewalt
Type / number of model	Dewalt DC305 with date codes 200601-49 through 200640-49
Risk type	Fire
Risk description	This product poses a risk of fire because the switch on this saw can short-circuit.
Country of origin	Mexico
Measures taken by economic operators	Other : Voluntary recall from consumers Other

Alert number 0166/07



Notifying country	Germany
Product category	Cosmetics
Type	Consumer
Product	Shower gel – Tropical Dream, skin-neutral pH
Brand	Soft & Gentle
Type / number of model	1. CH.Nr. 301, PROD 08.06, MHD, best-before date 02.09; 2. CH.Nr. 636, PROD 07.05, MHD, best-before date 01.08.
Risk type	Microbiological
Risk description	This product poses a serious bacteriological risk because the product contains a high concentration of microbe <i>Pseudomonas aeruginosa</i> . Use of cosmetics containing pathogenic microbe <i>Pseudomonas aeruginosa</i> may cause infection, especially when the skin is broken, leading to inflammation, suppuration and sepsis. Eye infections and inflammation of the ear may also result.
Country of origin	Germany
Measures taken by economic operators	Other : Voluntary recall from consumers by the manufacturer Other

Alert number 0165/07



Notifying country Czechia

Product category Toys

Type Consumer

Product Puzzle

Brand LXT 2193

Type / number of model No 331

Risk type Suffocation

Risk description This product poses a serious risk of suffocation because the bag made of flexible plastics with an opening perimeter greater than 380 mm has an average sheet thickness of 0,013 mm while it should have at least 0,038 mm. The thin plastics can adhere to mouth or nose of a child. Covering the face by a thin plastic can lead to suffocation. This toy does not comply with the Toys Directive and the relevant European standard EN 71-1.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Sales ban ordered by the authorities
Other

Alert number 0164/07



Notifying country Czechia

Product category Toys

Type Consumer

Product Puzzles

Brand LXT 1125 A

Type / number of model No. D-1


Risk type Suffocation

Risk description This product poses a serious risk of suffocation because the bag made of flexible plastic with an opening perimeter greater than 380 mm has an average sheet thickness of 0,017 mm while it should have at least 0,038 mm. The detected defect poses a high risk for children. Covering the face by a thin plastic can lead to suffocation. This toy does not comply with the Toys Directive and the relevant European standard EN 71-1.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Sales ban ordered by the authorities
Other

Alert number 0163/07



Notifying country	United Kingdom
Product category	Motor vehicles
Type	Consumer
Product	Mini motorbike
Brand	Unknown
EC-type approval/model	Unknown
Risk type	Injuries
Risk description	The product poses a serious risk of injuries because: - there is insufficient guarding of the engine drive chain and rear-most sprocket; - the fuel is vented via the filler cap directly in front of the rider which has health, machine control and fire hazard implications; - the engine stop has no additional action to re-set; - the handlebar levers are not ball ended; - the free movement of the steering mechanism is being fouled by mis-aligned body parts; - sharp edges are also present; - no user manual is supplied with the machine. The product does not comply with the Machinery Directive.
Country of origin	Unknown
Measures taken by economic operators	Other : Ban of sales ordered by the authorities. Voluntary withdrawal from the market by the retailer Other

Alert number 0162/07



Notifying country United Kingdom

Product category Motor vehicles

Type Consumer

Product Mini motorbike

Brand Unknown

EC-type approval/model Unknown

Risk type Injuries

Risk description This product poses a risk of injuries because: - there is insufficient guarding of the engine drive chain and rear-most sprocket; - the fuel is vented via the filler cap directly in front of the rider which has health, machine control and fire hazard implications; - the fuel pipe and tank were insecure; - the engine stop has no additional action to re-set; - the handlebar levers are not ball ended; - there was no reserve travel on the off-side brake operating lever (front brake) which means that it cannot achieve full braking efficiency if required; - the free movement of the steering mechanism was being fouled by mis-aligned body parts. The product does not comply with the Machinery Directive.

Country of origin Unknown

Measures ordered by public authorities Other : Product destruction ordered by the authorities
Other

Alert number 0128/07



Notifying country Slovenia

Product category Machinery

Type Consumer

Product Hydraulic trolley jacks

Brand TOPEX

Type / number of model Hydraulic trolley jacks TOPEX 2t PH 200

Risk type Injuries

Risk description This product poses a risk of injuries to the user or a third person since it is possible to use it incorrectly to lifting given the non-compliant users manual and marking on the product. In particular: - the original instructions or the translation into Slovenian do not contain the required information; - the instructions translated from Polish are essentially shortened and do not include the contents of the control book; - the marking and warnings on the product are inadequate. This product does not comply with the Machinery Directive and the relevant European standards.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Sales ban and withdrawal from the market ordered by the authorities
Other

Alert number 0127/07



Notifying country Slovenia

Product category Machinery

Type Consumer

Product Hand winch

Brand Hand winch "HANDSEIL WINDE"

Type / number of model Hand winch 800 HM Müller, Art. Nr. W16-0,6

Risk type Injuries

Risk description This product poses a risk of electric shock because: - the machine does not have an appropriate brake for lowering of lifted 600 kg loads; - the ropes do not have a working coefficient of 5; - the instructions for use do not comply with the requirements and can lead to dangerous situations. This product does not comply with the Machinery Directive and the relevant European standards.

Country of origin Unknown

Measures ordered by public authorities Other : Sales ban and withdrawal from the market ordered by the authorities
Other

Alert number 0121/07

Notifying country Greece

Product category Motor vehicles

Type Consumer

Product Heated windscreen earth point

Brand Ford

EC-type approval/model Passengers' cars, models C-MAX & GALAXY

Risk type Fire

Risk description The product poses a risk of fire because the affected vehicles may not have the heated windscreen earth point tightened to the specification. An incorrectly tightened bolt may lead to electrical arcing and in some cases the arcing may cause scorching or burning of the surrounding trim components.

Country of origin Belgium

Measures taken by economic operators Other : Voluntary corrective actions taken by the importer
Other