

Alert number **[0504/07](#)**

Notifying country **Greece**

Product category **Motor vehicles**

Type **Consumer**

Product **Passenger car - DPF (Diesel Particulate Filter) system in Suzuki Grand Vitara**

Brand **SUZUKI**

EC-type approval/model **Suzuki Grand Vitara Turbodiesel 1.9**

Product description **The recall concerns vehicles with chassis numbers from JSAJTA44V00107438 to JSAJTA44V00251487 (3D) and from JSAJTD44V00106868 to JSAJTD44V00252271 (5D), with production period from 28 June 2005 to 2 April 2007.**

Risk type **Injuries**


Risk description **This vehicle poses a risk of injuries due to a possible loss of power. The affected vehicles may pose a potential risk of damage to DPF (Diesel Particulate Filter) system. Due to the improper design of the intercooler and the intercooler inlet hose, the compressed air could leak and cause the improper ratio of air/fuel mixture. After certain period of usage, the above condition may cause excessive deposition of carbon particulate in DPF that could result in the overheating or melting of DPF and damage due to heat. In this case the warning lights on drivers control panel will illuminate and if the vehicle will not be driven to an authorised repair, loss of power will happen.**

Country of origin **Japan**

Measures taken by economic operators **Other : Voluntary corrective actions taken by the importer  
Other**

Alert number

**0503/07**



Notifying country

**Slovenia**

Product category

**Electrical appliances and equipment**

Type

**Consumer**

Product

**Conversion adaptor**

Brand

**OBI**

Barcode

**4017442505020**

Product description

**Conversion adaptor is made from white plastic and has four plugs.**

Risk type

**Electric shock  
Fire**

Risk description

**This product poses a risk of electric shock and fire because:**  
**- it is possible to insert only one pin of an europlug into the socket-outlet part of the adaptor while other pin is freely accessible;**  
**- insulating material of a plug part of adaptors fails to meet the requirements of glow wire test at 750 °C. Flames (burning) are still present 30 second after removal of glow wire;**  
**- required markings are missing (MAX rating stated for current or power, type reference). This product does not comply with the Low Voltage Directive and the relevant standards.**

Country of origin

**Germany**

Measures taken by economic operators

**Other : Voluntary withdrawal from the market and recall from consumers by the distributor  
Other**

Alert number

**0502/07**



Notifying country	<b>France</b>
Product category	<b>Protective equipment</b>
Type	<b>Consumer</b>
Product	<b>Alcohol tester - "Innovative consumer components" alcohol tester</b>
Brand	<b>UNITRONIC GMBH &amp; CO. KG</b>
Product description	<b>REFERENCE CONRAD: 853729, GENCOD: 4016138090901, ICC 2004-D-DUC, INTERNATIONAL SALES: REF 853729-I5 Unknown</b>
Risk type	<b>Injuries</b>
Risk description	<b>The product poses a risk of injuries due to its inability to detect a positive alcohol level resulting in a risk of user driving with undetected excessive alcohol level. The product does not comply with the relevant national standard NF X 20-704.</b>
Country of origin	<b>Germany</b>
Measures taken by economic operators	<b>Other : Voluntary stop of sales, withdrawal from the market and information to consumers Other</b>

Alert number **0501/07**



Notifying country **Estonia**

Product category **Toys**

Type **Consumer**

Product **Plastic toys - Set of three squeezable toys "Lovely Collection"**

Brand **Lovely Collection**

Type / number of model **93061/KP9851-3C (829)**

Barcode **5905698985118**

Product description **The set of toys consists of three coloured and flexible plastic animal figures (donkey, bear, tiger). Toys are about 10 cm tall and have a peeping whistle. The set of toys is in the plastic bag with a colourful label on it with the inscription: "Lovely Collection, Non toxic, CE mark, Made in China".**

Risk type **Chemical**

Risk description **This product poses a chemical risk because it contains 41,5 % by weight of di-isononyl phthalate (DINP), which exceed the allowed maximum limit of 0,1 % by weight set in the Chemicals Restrictions Directive 76/769/EEC.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Withdrawal from the market and recall from consumers ordered by the authorities  
Other**

Alert number **0500/07**



Notifying country **Slovenia**

Product category **Motor vehicles**

Type **Consumer**

Product **Mini motorbike**

Brand **Unknown**

EC-type approval/model **Unknown**

Product description **Net weight: 24 kg. Dimensions 1050 mm x 600 mm x 380 mm. Given as a gift if you buy a Ryobi set of drilling machine, vacuum cleaner for car and filler.**

Risk type **Burns  
Cuts  
Injuries**

Risk description **This product poses a serious risk of burns, cuts and injuries because : - the chain guard is insufficient and therefore there is a danger that the rider will come into contact with the chain; - there are sharp edges all over the bike; - electrical wiring is exposed to chafing. This product does not comply with the Machinery Directive.**

Country of origin **People's Republic of China**

Measures taken by economic operators **Other : Voluntary withdrawal from the market. Distribution ban ordered by the authorities  
Other**

---

Alert number **[0499/07](#)**

---

Notifying country **Sweden**

Product category **Motor vehicles**

Type **Consumer**

Product **Passenger car - Volvo C70**

Brand **Volvo**

EC-type approval/model **2007-model vehicles are affected, chassis number:  
0014876-0023851**

Product description **Unknown**

Risk type **Injuries**

Risk description **An incorrect temporary assembly instruction has been discovered resulting in an incorrect assembly of the left door handle Bowden cable attachment. This incorrect assembly may result in the left door not meeting the legal requirements at a certain collision scenario.**

Country of origin **Unknown**

Measures taken by economic operators **Other : Voluntary corrective action taken by the manufacturer  
Other**

Alert number **0498/07**

Notifying country **Sweden**

Product category **Motor vehicles**

Type **Consumer**

Product **Passenger car - Volvo V50**

Brand **Volvo**

EC-type approval/model **2007 model vehicles are affected, chassis number:  
0306047-0307754**

Product description **Unknown**

Risk type **Injuries**

Risk description **This product poses a serious risk of injuries because certain spot welds in the roof area may deviate from the specification. This deviation may weaken the brackets for the front and rear load net fixations. At certain driving conditions, such as a sudden braking, the driver and passengers may be exposed to the risk of being hit by projected load.**

Country of origin **Sweden**

Measures taken by economic operators **Other : Voluntary corrective actions taken by the manufacturer  
Other**

Alert number **[0497/07](#)**



Notifying country **The Netherlands**

Product category **Cosmetics**

Type **Consumer**

Product **Nail polish**

Brand **Laneche**

Type / number of model **08 27708 1862, 09 22709 3493**

Product description **Producer Identification No: UK 21120 (040140) and UK 13959 (380930) .Laneche Nail Enamel is packed in a gold coloured box. The box contains the bottle of 11 ml with the nail enamel. The batch codes are located on the bottom of the bottles.**

Risk type **Chemical**

Risk description **This product poses a chemical risk because it contains 0.2 % and 5.4 % of Dibutyl Phthalate. The use of Dibutyl Phthalate is prohibited in cosmetics by the Cosmetics Directive 76/768/EEC. Dibutyl Phthalate may cause harm to unborn children and impaired fertility. Phthalates have a negative effect on the development of male/female reproductive organs. Especially children are vulnerable as their body is developing and can be negatively affected by these toxic substances.**

Country of origin **United Kingdom**

Measures taken by economic operators **Other : Voluntary withdrawal from the market.  
Administrative fine ordered by the authorities  
Other**

Alert number **0496/07**



Notifying country **Estonia**

Product category **Toys**

Type **Consumer**

Product **Set of bath toys - 'Duck family'**

Brand **Bath Toy**

Type / number of model **Item No 93061/KN2304, bar code 5905698230447**

Product description **Set of four yellow coloured and flexible plastic duck-shaped figures. The toys have a peeping whistle. The set of toys is in the plastic net with a colourful tag on it with the inscription: "Bath Toy, CE mark, for ages over 3 months, Made in China".**

Risk type **Chemical**

Risk description **This product poses a chemical risk because it contains 37,1 % by weight of di-isononyl phthalate (DINP), which exceed the allowed maximum limit of 0,1 % by weight set in the Chemicals Restrictions Directive 76/769/EEC restricting the marketing and use of certain dangerous substances.**

Country of origin **People's Republic of China**

Measures taken by economic operators **Other : Voluntary withdrawal from the market and recall from consumers by the importer  
Other**

Alert number

**0495/07**



Notifying country **United Kingdom**

Product category **Toys**

Type **Consumer**

Product **Plastic toys - Squeaky Nessie Toys**

Brand **Unknown**

Type / number of model **7020**

Product description **Green Plastic Squeaky Nessie Toy - shape like a dragon**

Risk type **Chemical  
Choking**

Risk description **This toy poses a serious risk of choking because: - the tail can be detached on the application of a 90 N tensile force and fitted entirely in the small parts cylinder, presenting a choking hazard for children under three years if swallowed; - the sound mechanism could easily be removed and would constitute a choking hazard to children under 36 months. This toy also poses a chemical risk because it contains diisononyl phthalate (DINP) which is banned for use in toys which can be placed in the mouth. The design of this article is such that the toy could be easily mouthed. The toy does not comply with the Toys Directive, the Chemicals Restrictions Directive 76/769/EEC and the relevant European standard EN 71-1.**

Country of origin **People's Republic of China**

Measures taken by economic operators **Other : Voluntary withdrawal from the market, recall from suppliers and information to consumers by the importer**

## Other

Alert number **0494/07**



Notifying country **Bulgaria**

Product category **Cosmetics**

Type **Consumer**

Product **Hair care lotion**

Brand **Anticedin forte; Anticedin**

Type / number of model **Bar code: 4820001410112 and 4820028080107**

Product description **Unknown**

Risk type **Chemical**


Risk description **This product contains lead acetate up to 0,6 % (written on the list of ingredients) which is prohibited by the Cosmetics Directive 76/768/EEC.**

Country of origin **Ukraine**

Measures ordered by public **Other : Sales ban and recall from consumers ordered by the**

authorities

**authorities**  
**Other**



Alert number **0493/07**



Notifying country **Austria**

Product category **Clothing, textiles and fashion items**

Type **Consumer**

Product **Children's blouses**

Brand **TIK & TAK Smile**

Type / number of model **TIK & TAK Smile, Item No: 3.145.4122-32; Tunic blouse, Sizes 86 to 122, Item No: 3.145.4123**

Product description **Children's blouses with cords at the collar**

Risk type **Suffocation**

Risk description **The products pose a risk of suffocation through strangulation. According to the relevant European standard, garments intended for young children (children until the age of 7 years) shall not be designed, manufactured or supplied with drawstrings, functional cords or decorative cords in the hood or neck area. These products do not comply with the relevant European standard.**

Country of origin **Unknown**

Measures taken by economic operators **Other : Voluntary withdrawal from the market by the importer  
Other**

Alert number **0492/07**



Notifying country **Ireland**

Product category **Motor vehicles**

Type **Consumer**

Product **Motorcycle - KTM 990 Adventure ABS**

Brand **KTM**

EC-type approval/model **LC8 990 Adventure ABS Production**

Product description **Motorcycle produced between December 2005 and January 2007**

Risk type **Injuries**

Risk description **This product poses a serious risk of injuries because investigations have shown that in certain riding conditions vibrations transmitted from the chassis to the rear brake hydraulic lines can create a phenomenon whereby gas is released from the brake fluid and collecting in pockets of gas in the hydraulic lines. Any pockets of gas within the hydraulic circuit of the rear brake will significantly reduce the effectiveness of the system and in extreme cases will render the rear brake inoperative.**

Country of origin **Austria**

Measures taken by economic operators **Other : Voluntary recall from consumers and corrective actions taken by the importer  
Other**

Alert number **[0491/07](#)**



Notifying country **Slovenia**

Product category **Electrical appliances and equipment**

Type **Consumer**

Product **Conversion adaptor**

Brand **KOPP**

Barcode **4008222958327**

Product description **Conversion adaptor made from white plastic which has three parts plugs**

Risk type **Electric shock  
Fire**

Risk description **This product poses a risk of electric shock and fire because:  
- it is possible to insert only one pin of an europlug into the socket-outlet part of the adaptor while other pin is freely accessible; - required markings are missing (MAX rating stated for current or power, type reference). This product does not comply with the Low Voltage Directive and the relevant standards.**

Country of origin **Germany**

Measures taken by economic operators **Other : Voluntary actions taken by the distributor: recall from consumers, destruction of the product and information to consumers  
Other**

Alert number **[0490/07](#)**

Notifying country **Poland**

Product category **Motor vehicles**

Type **Consumer**

Product **Passenger cars - Fiat Ulysse and Lancia Phedra**

Brand **Fiat, Lancia**

EC-type approval/model **2,2 JTD Fiat Ulysse of series from type 3001046 to 3201942, Lancia Phedra 2.0 of series from type 3002175 to 3202476**

Product description **- 2,2 JTD Fiat Ulysse produced in the period between August 2002 and December 2004; - Lancia Phedra 2.0 produced in period between October 2002 and December 2004.**

Risk type **Injuries**

Risk description **This product poses a serious risk of injuries because water, which turns into ice at low temperatures, can get into the Exhaust Gas Recirculation (EGR) valve damaging the valve and making it leaky. The valve is located on the intake manifold and plays a key role in reducing unwanted engine emissions. When the valve is flawed it can cause excessive emissions of exhaust gases, engine's choking and stalling while accelerating and finally lowering efficiency of the braking system.**

Country of origin **Italy**

Measures taken by economic operators **Other : Voluntary information to consumers and corrective actions taken by the importer  
Other**

Alert number

**0489/07**



Notifying country

**Germany**

Product category

**Electrical appliances and equipment**

Type

**Consumer**

Product

**Glue gun**

Brand

**REINEX**

Type / number of model

**8118**

Barcode

**4068400081186**

Product description

**Inscriptions on the device: Glue Gun 40W, 220V~240V  
50Hz/60Hz**

Risk type

**Electric shock**

Risk description

**This product poses a risk of electric shock because device failed the voltage stability test. In addition, dimensions of the Europlug do not comply with the requirements of the standard. There is no symbol for appliances in Protection Class II. This product does not comply with the Low Voltage Directive and the relevant European standards.**

Country of origin

**People's Republic of China**

Measures taken by economic operators

**Other : Voluntary withdrawal from the market and recall from consumers by the supplier  
Other**

Alert number **0488/07**



Notifying country **Germany**

Product category **Lighting equipment**

Type **Consumer**

Product **Ceiling light - Florentiner Krone Verona ceiling light**

Brand **Unknown**

Type / number of model **Neckermann Item No 097/562**

Product description **Light with five bulbs — Florentiner Krone "Verona"**

Risk type **Electric shock**

Risk description **Because of faulty assembly, an active cable (live cable) is trapped between the metal parts of the light. The basic insulation of the cable has been severed and the metal parts of the light (casing) become live when the light is switched on. This product does not comply with the Low Voltage Directive and the relevant European standard.**

Country of origin **Italy**

Measures taken by economic operators **Other : Voluntary withdrawal from the market and recall from consumers by the distributor  
Other**

Alert number

**0487/07**



Notifying country

**Ireland**

Product category

**Electrical appliances and equipment**

Type

**Consumer**

Product

**AC Power Adaptor for 3108 Wireless phone (only the adaptor poses a safety risk)**

Brand

**3Com**

Type / number of model

**3C10408A (3108 Wireless Phone), DSA-10P-05 (AC Power Adaptor)**

Product description

**The adaptor plugs are used with the AC Power Adaptor and supplied with 3108 Wireless Phone; are manufactured by DVE (Model DSA-10P-05). The Adaptor for use in the United States does not have the manufacturing defect and is safe to use, however, the UK, Australia and EU power plugs which were supplied with this wireless phone system have the reported defects. The same adaptor is shipped to all countries. There is one cord and power supply box, the various plug form factors snap on and off the power supply box. The US snap on adaptor is safe; the UK, Australian and EU adaptors had design and manufacturing defects. The affected power adaptor can be identified by the following markings: "DVE ® Switching Adaptor Model DSA-10P-05".**

Risk type

**Electric shock**

Risk description

**This product poses a serious risk of electric shock because the removal of the adaptor from the electric socket caused part of the adaptor to break off, exposing internal parts and posing a risk of electric shock. The risk can be posed by the UK, Australia and EU adaptor plugs. This product does not comply with the Low Voltage Directive. One**


**incident was reported in the United Kingdom.**

Country of origin

**People's Republic of China**

Measures taken by economic operators

**Other : Voluntary stop of sales and recall from consumers taken by the producer**  
**Other**



Alert number **0486/07**



Notifying country **France**

Product category **Lighting equipment**

Type **Consumer**

Product **Portable luminaire - luminous house made of porcelain (Christmas decoration)**

Brand **Unknown**

Type / number of model **100 00090687**

Product description **Supplier's model number: lh307/yh0501/yh0502; Gencod: 3660092491147 Luminaire for outside use consisting of a 4-m lighting tube rolled onto a structure in the form of a lantern. Dimensions 21.5 x 21.5 x 24.5 cm. Exists in white light, in various colours or multicoloured. The item is marked: "Decorative lighting harness - model LH 307 - Bulb type E14 230V 7 W TRI ACE CABLE.**

Risk type **Electric shock**

Risk description **This product poses a risk of electric shock because: - luminaire class 0 (cable with simple insulation) is banned by the standard; - there is no cord anchorage in the switch; - the bulb holder indicates 125V whereas the luminaire uses 230V; - there is no warning for a type y fixture. This product does not comply with the Low Voltage Directive and the relevant European standards.**

Country of origin **People's Republic of China**

Measures taken by economic operators **Other : Voluntary withdrawal from the market by the distributor**

## Other

Alert number **0485/07**



Notifying country **Finland**

Product category **Clothing, textiles and fashion items**

Type **Consumer**

Product **Children's raincoat**

Brand **Unknown**

Type / number of model **STL-1, PINK/864**

Product description **Children's raincoat. Many sizes and colours. Label indicates that the products were treated with 3M Scotchlite.**

Risk type **Injuries**

Risk description **The product poses a serious risk of injuries due to possible entrapment of cords. In particular, drawstring on the lower edges of garments, where the lower edge is situated below the hip, hang below the lower edge of the garment although they should be totally inside the garment and not hang below the lower edge of the garment. This product does not comply with the relevant European standard EN 14682.**

Country of origin **People's Republic of China**

Measures taken by economic operators **Other : Import of the product rejected by the customs authorities and voluntary corrective actions taken by the importer  
Other**

Alert number **0484/07**



Notifying country **Bulgaria**

Product category **Childcare articles and children's equipment**

Type **Consumer**

Product **Soothers with chain**

Brand **“Jodow”**

Type / number of model **Unknown**

Product description **Soothers with silicon teat and chain**

Risk type **Choking**

Risk description **This product poses a risk of choking because when pulling off the teat from the ring it becomes detached while applying force less than 50 N. This product does not comply with the relevant European standard.**

Country of origin **Syria**

Measures ordered by public authorities **Other : Sales ban, withdrawal from the market and information to consumers ordered by the authorities. Press release has been issued.  
Other**

Alert number **0483/07**



Notifying country **Bulgaria**

Product category **Childcare articles and children's equipment**

Type **Consumer**

Product **Soothers**

Brand **Camera**

Type / number of model **5557**

Barcode **4711146155573**

Product description **Soothers, brand "Camera", silicon teat**

Risk type **Choking**

Risk description **The product poses a risk of choking because: - the shield is too small and easily fits into the small parts cylinder; - when the ring is being pulled off the shield at the right corner, the first side of the ring is detached applying a force less than 50 N, and all other parts become detached with force less than 90 N at stage of holding. This product does not comply with the relevant European standard.**

Country of origin **Taiwan**

Measures ordered by public authorities **Other : Sales ban, withdrawal from the market and information to consumers ordered by the authorities. Press release has been issued.  
Other**

Alert number **0482/07**



Notifying country **Bulgaria**

Product category **Clothing, textiles and fashion items**

Type **Consumer**

Product **Shoes - Ladies' boots**

Brand **Unknown**

Type / number of model **6199-2**

Product description **Ladies' boots, green colour, with plastic label tagged to the tongue, with the following indication: "AB ANCHOR BLUE", with sewed textile band around the foot with indication: "Al BgANA SPORT". Packaging: pink box indicating: "art. # 6199-2" and "KRASEL"**

Risk type **Chemical**

Risk description **The product poses a chemical risk because the textile components of the shoes contain a high level of 384,8 mg/kg of formaldehyde, which exceed the maximum amount of 75 mg/kg. This can cause irritations and allergic reactions and is therefore dangerous for the health and safety of consumers. Formaldehyde has low allergic potential, i.e. allergic reactions may be caused by small amounts of formaldehyde.**

Country of origin **Unknown**

Measures ordered by public authorities **Other : Sales ban, withdrawal from the market and information to consumers ordered by the authorities. Press release has been issued.  
Other**

Alert number **0481/07**



Notifying country **Finland**

Product category **Clothing, textiles and fashion items**

Type **Consumer**

Product **Long sleeve T-shirt and pants**

Brand **Chili, Ghetto Fabulous**

Type / number of model **NT433**

Product description **Long sleeve T-shirt with zip and pants. Different colours and sizes**

Risk type **Injuries**

Risk description **The product poses a serious risk of injuries, due to possible entrapment of cords because: - drawstring in waist area of trousers is not fastened; - there are protruding drawstrings in bottom hem of trousers. This product does not comply with the relevant European standard EN 14682.**

Country of origin **Bangladesh**

Measures taken by economic operators **Other : Import of the product rejected by the customs authorities and voluntary corrective actions taken by the importer  
Other**

Alert number **0480/07**

Notifying country **Greece**

Product category **Motor vehicles**

Type **Consumer**

Product **Parking brake system in passenger car Suzuki Swift**

Brand **SUZUKI**

EC-type approval/model **Swift 1.3 & 1.5 (code of recall: "HUGJ")**

Product description **The recall concerns vehicles with chassis numbers: - from TSMMA11S00114437 to TSMMA11S00334706 (1.3, 3-doors), - from TSMMA11S00100137 to TSMMA11S00334612 (1.3, 5-doors), - from TSMMA21S00136455 to TSMMA21S00202342 (1.5)**

Risk type **Injuries**

Risk description **The affected vehicles may have a potential risk of malfunction in the parking brake system. The parking brake cable end and parking brake shoe lever may be assembled incorrectly. There is a possibility that the parking cable brake end will detach from the parking brake shoe lever. In this situation the effectiveness of the parking brake will be lost.**

Country of origin **Hungary**

Measures taken by economic operators **Other : Voluntary corrective actions taken by the importer  
Other**

Alert number **0479/07**



Notifying country **The Netherlands**

Product category **Hobby/sports equipment**

Type **Consumer**

Product **Seatpost - Bicycle component**

Brand **Selcof**

Type / number of model **SP n° 46, n° 48 (enkelbouts), Selcof type n° 54, n° 58 (dubbelbouts), Italy. Advance: '02, '03; Adventure: '01, '02; Confidence: '03; CityLiner: '03, '04; Forrest: '01, '02; LiteAce: '01, '02; RoadGentlemen: '01, '02, '03; RoadLady: '01, '02, '03; RoadRunner: '01, '02, '03; TerraLiner: '01, '02, '03; Traveller: '01, '02, '03; Accellance: '03, '04; Alliance: '03, '04, '05; GrandTour: '01, '02, '03, '04; GlobeTraveller-s: '01; RoadRunner-C: '01, '02; Excellence: '02, '03, '04; SilverAce: '04**

Product description **Seat-post Selcof type SP n° 46, n° 48 (enkelbouts) and Selcof type n° 54, n° 58 (dubbelbouts)**

Risk type **Injuries**

Risk description **This product poses a serious risk of injuries because the bolt attaching the seat snaps. If the seat position is adjusted without sufficiently loosening the bolt, wear is caused to the teeth. The teeth ensure a so-called closed construction. The bolt's sole function is to hold the whole construction together, and it is subject to a pure tensile stress. The wear creates microscopic gaps, causing the teeth to wear even more, eventually causing the bolt to be subjected to lateral stresses which can cause it to snap. Wear on the teeth can also be caused by an incorrect bolt tightening torque. The position of the seat also affects the**


**nature of the stress imposed. Incidents have been reported.**

Country of origin

**Italy**

Measures taken by economic operators

**Other : Voluntary withdrawal from the market  
Other**




Alert number **0478/07**



Notifying country	<b>Spain</b>
Product category	<b>Toys</b>
Type	<b>Consumer</b>
Product	<b>Pack of three toy mobile phones</b>
Brand	<b>Color Baby</b>
Type / number of model	<b>3281</b>
Barcode	<b>8412842032811</b>
Product description	<b>Three toy mobile telephones with different forms. One is blue, another grey and the third is grey and black. They are sold in a blister pack, and the labelling includes the following statements: "Color Baby" Happy Phone with light and sound. Attention: not recommended for children under the age of 36 months: small parts. Keep instructions. Do not mix new and old batteries. Distributed by Color Baby, ref 3281".</b>
Risk type	<b>Choking</b>
Risk description	<b>This product poses a risk of choking because the button batteries are accessible without the aid of a tool, and the cover can be opened without executing at least two movements simultaneously. This toy presents an asphyxia hazard if the batteries are swallowed. This toy does not comply with the Toys directive and the relevant European standards EN 71-1 and EN-50088.</b>
Country of origin	<b>People's Republic of China</b>

Measures ordered by public  
authorities

**Other : Withdrawal from the market ordered by the  
authorities  
Other**



Alert number **0477/07**

Notifying country **Spain**

Product category **Motor vehicles**

Type **Consumer**

Product **Passenger car - Polo**

Brand **Volkswagen**

EC-type approval/model **POLO, PR series.**

Product description **Chassis numbers between: WVW ZZZ 9NZ 64 000 001-261502 and WVW ZZZ 9NZ 64000 001-163395 .Vehicles, model saloon car built between May 2005 and February 2007 .**

Risk type **Fire**

Risk description **This product poses a serious risk of fire because in model saloon cars with heated seats, sports seats and "comfort" seats there is a possibility of a short circuit occurring in the heating mats of the seats because the tips of the wires are not sewn in correctly. The covers of the front seat backs can sustain burn damage.**

Country of origin **Spain**

Measures taken by economic operators **Other : Voluntary corrective actions taken by the importer  
Other**

Alert number **0476/07**

Notifying country **Portugal**

Product category **Motor vehicles**

Type **Consumer**

Product **Motorbike Honda NVS50 Today**

Brand **Honda**

EC-type approval/model **NVS 50 Today**

Product description **VINs: LALAF61A\*3000023 - LALAF61A\*3003988, LALAF611\*0000000 - LALAF611\*9999999, AF61-1095014 - AF61-1299103 NVS 50 Today 2004 and 2006 model year**

Risk type **Injuries**

Risk description **This product poses a serious risk of injuries because the speedometer cable on the units affected may break and prevent the speedometer displaying the speed. Inspection of a speedometer cable and a brake panel revealed a split in the outer lining material (PVC), with corrosion of the winding of the outer structure and the inner winding at the area of the split, causing the speedometer reel to seize up and break. Reproduction tests revealed that certain components of the grease applied to the sliding surface of the inner cable caused hardening of the outer lining material, which might then split. If water enters through the split, the winding of the outer body and the inner cable corrode and seize up. The speedometer then breaks down when the speedometer reel or inner cable break.**

Country of origin **People's Republic of China**

Measures taken by economic operators **Other : Voluntary recall from consumers and corrective actions taken by the importer  
Other**

Alert number **[0475/07](#)**



Notifying country	<b>Germany</b>
Product category	<b>Electrical appliances and equipment</b>
Type	<b>Consumer</b>
Product	<b>Travel adaptor, plug adaptor</b>
Brand	<b>Teleadapt Wonpro PWR 1153</b>
Barcode	<b>6660094153088</b>
Product description	<b>White plug adaptor, bearing the following inscription: "Wonpro PAT. CE. Travel Universal Adaptor with safety shutter"</b>
Risk type	<b>Electric shock</b>
Risk description	<b>This product poses a risk of electric shock because: - it is possible to make a connection between the pin of a plug and an active part of the adaptor socket while another pin can be touched; - the non-insulated pins of the plug with earthing contact can be touched when the plug is partially inserted into the adaptor socket; - it is possible to insert a plug for Class I devices (with earth terminal) into the adaptor socket, which is designed exclusively for the insertion of plugs for Class II devices (with protection of connections without earth terminal). This product does not comply with the Low Voltage Directive.</b>
Country of origin	<b>People's Republic of China</b>
Measures taken by economic operators	<b>Other : Voluntary withdrawal from the market by the supplier Other</b>

Alert number **0474/07**



Notifying country **Finland**

Product category **Cosmetics**

Type **Consumer**

Product **Nail polish**

Brand **Black Onyx UV Glow**

Type / number of model **5330**

Product description **Nail polish with star-shaped particles**

Risk type **Chemical**

Risk description **This product poses a chemical risk because, according to its list of ingredients, it contains dibutyl phthalate which is prohibited in cosmetics. Dibutyl phthalate may cause harm to an unborn child and possibly pose a risk of impaired fertility. Phthalates have a negative effect on the development of male/female reproductive organs. Especially children are vulnerable as their bodies are developing and can be negatively affected by these toxic substances. This product does not comply with the Cosmetics Directive 76/768/EEC.**

Country of origin **The Netherlands**

Measures taken by economic operators **Other : Voluntary withdrawal from the market by the importer  
Other**

Alert number **[0473/07](#)**

Notifying country **Norway**

Product category **Motor vehicles**

Type **Consumer**

Product **Snowmobiles**

Brand **Polaris Industries Inc.**

EC-type approval/model **Polaris FS and FST Snowmobiles**

Product description **model year 2006Unknown**

Risk type **Injuries**

Risk description **This product poses a risk of injuries because the welding process to manufacture the upper front shock tower brackets may not have achieved sufficient weld penetration in some instances. If insufficient weld penetration were to occur, there is a possibility that the upper shock mount could begin to separate at the welded joint(s). If a separation of the welded joint(s) were to occur, the most likely case would be that this occurs gradually. The ride height of the machine would gradually diminish as the location of the upper shock mount moved upwards. This can occur either the right or left side. A less likely possibility is that the shock mount falls suddenly. If this occurs, the rider could lose control of the machine, either due to a sudden change in the ride height of the machine or due to interference with steering mechanism. The product does not comply with the Machinery Directive.**

Country of origin **United States**

Measures taken by economic operators **Other : Voluntary corrective actions taken by the producer  
Other**