

Alert number 0294/06



Notifying country United Kingdom

Product category Motor vehicles

Type Consumer

Product

Brand Unknown

Product description MOTOR VEHICLES - mini motorbike "Mini moto pocket bike"Type/number of model: WJF 50 - 3 on packaging. SQ40A - on instructions

Risk type Burns
Fire
Injuries

Risk description This machine is extremely dangerous to operate and is likely to cause injury to the rider and to any other persons in the vicinity of the machine. - The fuel tank is vented under and just in front of the rider of the machine, causing a situation whereby the rider will inhale petrol fumes. This is also compounded by the fact that there is a potential fire hazard if the rider of anyone nearby is smoking near the tank cap during the venting process. - The drive chain and sprocket were not sufficiently guarded. - Frontal chain guard that is fitted is insufficient and also has sharp edges. - The handle bar levers were insecure, incomplete and were not ball ended. - The exhaust was insufficiently shielded at the front. - There was no re-set on the engine stop. - There was no speed-limiting device present. - A user manual provided with the

mini motor bike is intended for other model.

Country of origin Hong Kong

Measures ordered by public authorities Other : Sales ban ordered by the authority.
Other

Measures taken by economic operators Other : Voluntary withdrawal from the market and recall from consumers.
Other

Alert number 0293/06

Notifying country Luxembourg

Product category Hobby/sports equipment

Type Consumer

Product

Brand Unknown

Product description Quick release device for front wheels of bicycles "Shimano"Type/number of model: HB 5501 (105), HB 5600 (105), HB 6600 (Ultegra), HB 7800 (Dura Ace), HB M756 (XT), HB M760 (XT), HB M765 (XT), HB M960 (XTR), HB M965 (XTR), DH 2N71 (Sport Dynamo), DH 3N71 (Sport Dynamo), DH 3D71 (Sport Dynamo), HB HF08 (Tandem). Shimano wheels that may be concerned: WH 7801 (Dura-Ace), WH 7801C (Dura Ace), WH 7801C50 (Dura Ace), WH 7801SL (Dura Ace), WH M965 (XTR), WH R600.Only products supplied after 1 November 2005 are concerned.

Risk type Injuries

Risk description In certain cases, the quick release device may fail or break after installation and positioning. If this happens when the bicycle is in motion, the rider may lose control, and this may result in serious injury.

Country of origin Japan

Measures taken by economic operators Other : Voluntary corrective action taken by the producer.
Other

Alert number 0289/06



Notifying country Hungary

Product category Toys

Type Consumer

Product

Brand Unknown

Product description Toy iron board (brand unknown) with metal standType/number of model: Bar code: 5996055314467.

Risk type Injuries

Risk description The distance between the components moving as scissor blades is not appropriate and as a result, the child's fingers can get trapped. The product does not comply with the Toy Directive and the relevant European Standard.

Country of origin People's Republic of China

Measures ordered by public authorities Other : Placing on the market of the product is prohibited by the authority.
Other