

Alert number **[0328/06](#)**



Notifying country **Lithuania**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Set of rattles "BABY TOYS"Type/number of model: NO.2006A and NO.2006B.**

Risk type **Choking**

Risk description **This product presents a risk of choking, because during the torque and tension tests some parts of the toy (metal balls, plastic grains) detached and they fit within the small parts cylinder. This product does not comply with the Toys Directive and the relevant European Standard.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Sales ban and withdrawal from the market ordered by the authority.
Other**

Alert number **0327/06**



Notifying country **Hungary**

Product category **Other**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Digital watch for children "Sport Tong Xin".Package: sealed cellophane.**

Risk type **Choking**

Risk description **This product poses a risk of choking because the back of the watch can be easily removed by hand without using any tools and the batteries become accessible. The battery does not have the required markings. This product does not comply with the relevant European Standards.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Sales ban and recall ordered by the authorities.
Other**

Alert number

0326/06



**PICTURE
NOT
AVAILABLE**





**PICTURE
NOT
AVAILABLE**

**PICTURE
NOT
AVAILABLE**

Notifying country **Slovakia**

Product category **Lighters**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Novelty lighters of various shapes**Description: 1. dog made of metal, 2. racing motorcycle, 3. car resembling AUDI TT, 4. T-rex with monkey sitting on its back, 5. Elephant with lighting effect, 6. pistol, 7. revolver "CAPTAIN", 8. Pendant in the shape of a mobile phone with a flip cover, 9. Pendant in the shape of a mobile phone with unfolding knives and bottle opener , 10. excavator, 11. telephone, 12. DENIX grinder , 13. horse rider on a stand 14. revolver PYTHON 357 *357 MAGNUM CTG.* 15. handgun - musket ROYCE 04375, ROER LIGHTER, 16. lion on a stand (ashtray) „The lighter of lion, HD 14287“, 17. pendant in the shape of a pistol ITALY ARMY RBERETTA, 18. Pendant in the shape of a standard deck of playing cards, 19. pistol INTERARMS ALEXANDRA/VA P99, WALTHER.

Risk type **Burns
Fire**

Risk description **Products pose a danger to small children (the lighter shapes comply with the definition of the novelty lighters in accordance with EN 13869) because they can attract children younger than 51 months of age, which leads to an increased risk of burns or fire.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Sales ban and warning of consumers ordered by the authority.
Other**

Alert number

0325/06



Notifying country **Belgium**

Product category **Lighters**

| | |
|--|--|
| Type | Consumer |
| Product | &nbsp; |
| Brand | Unknown |
| Product description | Novelty lighters of various shapes. Description: 1. An eagle attacking a snake with lighting effects, 2. Elephant on a stand ELEPHANT, 3. Loading truck with a round Safety Label sticker on the chassis, 4. Train (locomotive OLD TRAIN and a car with an image of a lion and a label with CIGARETTE CASE printed on it), length approx. 24 cm, height 7 cm, identified on the package as: JS-1926 5. Submarine on a stand labelled U - 518, length approx. 39.5 cm; 6. Pistol U.S 9 mm M9 - P. BARETTA , 7. Gun ROYAL SOLITE, 8. Gold car with black roof, 9. Airplane USA F 117, 10. Historical pistol, 11. Cow with sound effect, approx. 8 cm, 12. A shoe - summer sandal, length of approx. 7 cm, 13. Helicopter, EAN 859 037 90 43354, code - 04335 14. TOW TRUCK POLICE, USA, length 13 cm, EAN 406 63 40 3050, label on the package: CONEY HOME code 33290 15. Off-road motorbike, EAN 859 0379 04 3354 code 04323 16. Sailboat with Chinese label DING HAO SMOKING SET, Plain Sailing, 04- 8815, EAN 8590379043262, code - 04326. |
| Risk type | Burns Fire |
| Risk description | Products pose a danger to small children (the lighter shapes comply with the definition of the novelty lighters in accordance with EN 13869) because they can attract children younger than 51 months of age, which leads to an increased risk of burns or fire. |
| Country of origin | People's Republic of China |
| Measures ordered by public authorities | Other : Sales ban and warning of consumers ordered by the authority. Other |

Alert number **[0324/06](#)**



Notifying country **Hungary**

Product category **Furniture**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Folded wooden chair for children Type/number of model:
Bar code: 4 090002 431120.**

Risk type **Injuries**

Risk description **This product poses a risk of injuries (in particular to children's fingers) because: -there is no safety stop or locking mechanism against folding; -there is no safety distance between the single moving parts of the chair. This product does not comply with the Toys Standard.**

Country of origin **Unknown**

Measures ordered by public authorities **Other : Sales ban and recall ordered by the authority.
Other**

Alert number **[0323/06](#)**



| | |
|--|--|
| Notifying country | Lithuania |
| Product category | Toys |
| Type | Consumer |
| Product | &nbsp; |
| Brand | Unknown |
| Product description | Toy car a bear driver made of yellow and green hard plastic (Toy has a sticker with inscription: "NO. 1798, pen, FLASH")Type/number of model: 1798. |
| Risk type | Choking |
| Risk description | The product presents a risk of choking because during traction test some parts (head of the bear, claws, pendants) that all fit the small parts cylinder became detached. The product does not comply with the Toys Directive and the relevant European standard EN 71-1. |
| Country of origin | People's Republic of China |
| Measures ordered by public authorities | Other : Sales ban and withdrawal from the market ordered by the authority. Other |

Alert number **[0322/06](#)**



Notifying country **Hungary**

Product category **Toys**

Type **Consumer**

Product **Police toy set**

Name **"Police Force Yi Feng Toys"**

Brand **Unknown**

Type / number of model **Item no. 3913.**

Product description **Package: cardboard and plastic in the front.**

Risk type **Injuries**

Risk description **During the tension test the suction-cup which has 10 mm easily came off from the projectile thus it may pose a risk of injury. This product does not comply with the Toys Directive and the relevant European Standards.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Withdrawal from the market and recall ordered by the authority.
Other**

Alert number **0321/06**



Notifying country **Lithuania**

Product category **Lighting equipment**

Type **Consumer**

Product **Manual illuminator**

Brand **"Bottari"**

Type / number of model **Unknown.**

Risk type **Electric shock**

Risk description **The product poses a risk of electric shock because it suffers from insufficient fastening of the cable, the cross-section of main cable is smaller than required (0,43mm²), the product did not pass the bent test (all cable conductors broke down) and the marking does not comply with the requirements (wrong voltage indication, essential symbols are missing). The product does not comply with the Low Voltage Directive and the relevant European standard EN 60598.**

Country of origin **Unknown**

Measures ordered by public authorities **Other : Withdrawal from the market ordered by the authority.
Other**

Alert number **[0320/06](#)**

Notifying country **Germany**

Product category **Motor vehicles**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Motor vehicle - car "Toyota LandCruiser 90"Type/number of model: J9 EG-BE: e6*93/81*0023*.Description: Vehicles produced between 17 April 1996 and 6 January 1999 are affected.**

Risk type **Injuries**

Risk description **High dynamic stress can cause damage to the outer flange of the rear axle shaft. This can result in the flange breaking and the wheel being lost. 12 cases are known to have occurred in Europe but without causing damage to third parties.**

Country of origin **Unknown**

Measures taken by economic operators **Other : Voluntary worldwide corrective action taken by the producer.
Other**

Alert number **[0319/06](#)**



Notifying country **Spain**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Two toys consisting of arrows with suction cups.Brand: 1. Simba; 2. No brand.Type/number of model: 1. Model 7450 630; 2. Model 8010B.**

Risk type **Injuries**

Risk description **The products pose a risk of injury for the users as a result of the high level of kinetic energy of arrows discharged from the bow. During testing, it was found that the kinetic energy of the arrows (0,73J and 0,69J respectively) exceeds the maximum permitted in the European standard EN 71-1. The product does not comply with the Toys Directive.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Withdrawal from the market ordered by the authority.
Other**

Alert number **[0318/06](#)**



Notifying country **Spain**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Magnetic Games "3 in 1 - RAMAJUEGOS"Type/number of model: 2948/9839.**

Risk type **Cuts**

Risk description **The product presents a risk of cuts due to sharp edges exposed when the metal plate separates from the plastic support. During testing, it was found that separation can occur easily. The product does not comply with the Toys Directive and the relevant European standard EN 71-1. One incident has been reported.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Withdrawal from the market ordered by the authority.
Other**

Alert number **[0317/06](#)**



Notifying country **Belgium**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Pinocchio riding a bike "Niagara"Type/number of model: 0112 EAN Code - 8006708001129.Description: Pinocchio riding a bike.**

Risk type **Choking**

Risk description **The product presents a risk of choking because small parts may become detached. During testing, Pinocchio's nose which fits the small parts cylinder came off at a force of 16.8 Newtons. The product does not comply with the Toys Directive and the relevant European standard EN 71-1.**

Country of origin **Italy**

Measures ordered by public authorities **Other : Sales ban and recall ordered by the authority. Other**

Alert number **[0316/06](#)**



Notifying country **Belgium**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Pullable toy duck "Niagara - Mamma Papera Bis" Type/number of model: EAN Code - 8006708003116.**

Risk type **Choking**

Risk description **The product presents a risk of choking because small parts may become detached. During testing, Pinocchio's nose which fits the small parts cylinder came off at a force of 22.5 Newtons. The product does not comply with the Toys Directive and the relevant European standard EN 71-1.**

Country of origin **Italy**

Measures ordered by public authorities **Other : Sales ban and recall ordered by the authority.
Other**

Alert number **0340/06**



Notifying country **Finland**

Product category **Communication and media equipment**

Type **Consumer**

Product ** **

Name **Hi-Speed USB 2.0 Notebook Card"**

Brand **Belkin**

Type / number of model **Product package F5U222yy**

Barcode **7 22868 428726**

Product description **Notebook card "Belkin - Name: Hi-Speed USB 2.0 Notebook Card**

Risk type **Electric shock**

Risk description **This product poses a risk of electric shock when the mains plug is inserted to the plug adaptor which is connected to the socket-outlet. When connecting the supplied plug or the power supply unit to the extension plug, - the pins of the plug or of the power supply unit are accessible and - the plug and the power supply unit can be single-pole inserted to the extension plug such that the other pin is accessible.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Recall from consumers ordered by the authority.
Other**

Alert number **0339/06**



Notifying country **Spain**

Product category **Motor vehicles**

Type **Consumer**

Product **Passenger car**

Name **Toyota Lexus**

Brand **Toyota**

EC-type approval/model **Lexus RX 300, Lexus RX 330**

Product description **Produced between February 2003 and December 2004. Description: In Europe, only the RX 300 model has been sold. The chassis numbers of the vehicles concerned lie in the range between JTJHF31U#00001046 and JTJHF31U#02003018 (the # symbol stands for any digit between zero and nine).**

Risk type **Injuries**

Risk description **In the notified vehicles a small loss of brake fluid from the back of the brake cylinder may occur. If the leak continues, the warning light on the dashboard will illuminate and the brake pedal will feel spongy when depressed. However, an accident could result from the loss of brake fluid, irrespectively of whether or not the driver had been warned by the dashboard light.**

Country of origin **Japan**

Measures taken by economic **Other : Voluntary corrective actions taken by the importer.**

operators **Other**



Alert number **0338/06**



Notifying country **Spain**

Product category **Electrical appliances and equipment**

Type **Consumer**

Product ** **

Brand **Unknown**

Type / number of model **KA HL 6**

Product description **Portable heater "KALORIK"**

Risk type **Electric shock**

Risk description **This product poses a risk of electric shock because the internal wiring is not properly secured and can become detached from the connections, thus live parts may become accessible to the user. This product does not comply with the relevant European Standards.**

Country of origin **Belgium**

Measures ordered by public authorities **Other : Withdrawal from the market ordered by the authority.
Other**

Alert number **[0337/06](#)**



| | |
|--------------------------------------|--|
| Notifying country | United Kingdom |
| Product category | Gas appliances and components |
| Type | Consumer |
| Product | &nbsp; |
| Brand | Unknown |
| Product description | Portable Gas Heater "Pyramid" 1.3kWType/number of model: Importer's Part # E6300 gas canister heater (sticker to top). Manufacturer's Model # BDN 100 (right hand side panel). |
| Risk type | Injuries |
| Risk description | This product poses a risk of explosion resulting from: - leakage of gas from gas regulator (lack of gas soundness) and - leakage from copper gas supply pipe as a result of foreseeable damage to pipe in event of over-rotation of burner head due to broken plastic stops made from low grade material. The gas appliance failed to comply with the European Standard: (1) broken plastic studs leading to damage to gas inlet pipe and ignition insulation wire, (2) the soundness test was conducted at 6 bar and during the test a leak was observed on the regulator, (3) key information omitted, (4) key safety, usage and maintenance messages were omitted. |
| Country of origin | People's Republic of China |
| Measures taken by economic operators | Other : Voluntary withdrawal from the market and recall from consumers. Other |

Alert number **0336/06**



Notifying country **Hungary**

Product category **Gas appliances and components**

Type **Consumer**

Product ** **

Brand **Unknown**

Type / number of model **NGS 50 (DG)**

Product description **Gas convector "DEM RAD"**

Risk type **Chemical**

Risk description **The appliance during the normal installation, maintenance and operation due to the high level of carbon-dioxide content may endanger safety of user, may cause serious poisoning.**

Country of origin **Türkiye**

Measures ordered by public authorities **Other : Sales ban and recall from consumers
Other**

Alert number **[0335/06](#)**



| | |
|------------------------|--|
| Notifying country | United Kingdom |
| Product category | Childcare articles and children's equipment |
| Type | Consumer |
| Product | car seat |
| Name | Team Tex Basic Challenger Explorer with instruction set V1085E. |
| Brand | "Baby Start" |
| Type / number of model | Basic Challenger Explorer |
| Product description | Infant car seat "Baby Start" |
| Risk type | Injuries |
| Risk description | It was found that the instructions with regard to the reassembly of the product could result in the product being reassembled incorrectly. If seat is reassembled incorrectly then this is likely to result in serious injury if the vehicle is involved in an accident. - The text size is far too small to be easily read and understood. It is approximately 5pt and should be closer to 7.5pt as a minimum. - There are no airbag warning icons. - There is no annotated diagram identifying the parts and features of the child seat. - There is no diagram of a 3-point lap and diagonal belt - a crucial factor in clarifying what the consumer needs to know. - Forward facing and rearward facing car seat instructions should show the car seat's safety belt in colour - red for forward facing and blue for rearward facing. These instructions do not show the distinction. - The 'Adjusting the harness height to the child's shoulder height' section is |

not explicit enough, leaving a lot for consumers to work out for themselves. - There is no advice regarding the position of chest pads when forward facing and when rearward facing (which tend to be different). Chest pads are a safety feature. - Tightening a seat belt across a child seat of this design requires the slack being removed in two to three different places - before the 'lock-off can be applied. This instruction only shows one position. - The airbag warning can be found at the bottom of this column set aside from the rest of the 'Recommendations'. Ideally it should appear first with a warning symbol and universal airbag warning icon to ensure it isn't overlooked. Accident - During the accident, child was only properly restrained on one side due to the incorrect reassembly of chair and subsequent failure of a part of the chair.

Country of origin

France

Measures ordered by public authorities

Other : Withdrawal from the market ordered by the authority. (The withdrawal notice does apply to products supplied with instructions numbered V1085E and similar and does not apply to V1085G).

Other

Measures taken by economic operators

Other : Voluntary alteration of the instructions by the manufacturer.

Other

Alert number **0334/06**



Notifying country **Spain**

Product category **Childcare articles and children's equipment**

Type **Consumer**

Product ** **

Brand **Unknown**

Type / number of model **REALCE TOPPER F4/UNO (Groups 1, 2 and 3)**

Product description **Infant car seat "Safety Baby"**

Risk type **Injuries**

Risk description **Serious and even fatal injuries are possible due to inadequate restraint of the child following severe impact. The car seat does not ensure the protection required: - When the Group 1 seat is installed, the child can easily undo the part of the device that restrains its pelvis. - There is no illustration affixed securely to the seat showing the correct location of the restraining straps. This product does not comply with the ECE Regulation 44R03-04 concerning the approval of restraining devices for child occupants of power driven vehicles (Child restraint system).**

Country of origin **France**

Measures ordered by public authorities **Other : Withdrawal from the market ordered by the authority.
Other**

Alert number **0333/06**



| | |
|------------------------|---|
| Notifying country | Spain |
| Product category | Childcare articles and children's equipment |
| Type | Consumer |
| Product | &nbsp; |
| Brand | Unknown |
| Type / number of model | Funny |
| Product description | Infant car seat "WIND BABY" |
| Risk type | Injuries |
| Risk description | Serious and even fatal injuries are possible due to inadequate restraint of the child following severe impact. The car seat does not ensure the protection required: - Once the seats from group 1 have been installed, the child can easily loosen the part of the restraint that secures the pelvis. - The seat does not have a permanently affixed diagram in which the car seat appears and indicating the correct positioning of straps. - There is no instruction on whether to use the infant car seat with a seatbelt or what type of seatbelt to use. - The instructions are not provided in Spanish. - The instruction about weight groups does not have the visibility established by the standard. - The instructions for use are not illustrated by clear drawings or photographs. - There is no clear explanation of how the buckle works. This product does not comply with the ECE Regulation 44R03-04 concerning the approval of restraining devices for child occupants of power driven vehicles (Child restraint system). |

Country of origin

Italy

Measures ordered by public
authorities

**Other : Withdrawal from the market ordered by the
authority.
Other**

Alert number **0332/06**



Notifying country **Germany**

Product category **Decorative articles**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Plastic decorative articles - pointy/sharp-edged decorative pieces of plastic and plastic ice cubes with holes.Type/number of model: Art. Nr: 1519018 (red), 1519029 (green), 1519037 (colourless), 1519020 (yellow), 1519034 (orange), 1519008 (blue).**

Risk type **Choking**

Risk description **Product is laid down on the table as decorative material and may be mistaken for food (sweets) or mistakenly used as ice cubes. This product can be swallowed in whole. In addition, this product has sharp corners and edges which may cause injuries.**

Country of origin **Unknown**

Measures taken by economic operators **Other : Voluntary recall of the product from consumers by importer. Distribution of the product was stopped by importer.
Other**

Alert number **[0331/06](#)**



| | |
|--|--|
| Notifying country | Hungary |
| Product category | Lighting equipment |
| Type | Consumer |
| Product | &nbsp; |
| Brand | Unknown |
| Product description | Salt crystal lamp "REALM"Type/number of model: DF-817. |
| Risk type | Electric shock Fire |
| Risk description | This product poses a risk of electric shock because: - the screw-type connection of the lamp holder is not secured against loosening, - the cable can get into contact with sharp edges, - the lamp holder can be easily pulled from the salt crystal. The product poses a risk of fire because the supporting surface is made of flammable material and the temperature was measured at 191,6 °C (permitted value: 90°C). This product does not comply with the LVD Directive and the relevant European Standards. |
| Country of origin | Pakistan |
| Measures ordered by public authorities | Other : Withdrawal from the market and recall ordered by the authority. Other |

Alert number **0330/06**



Notifying country **Lithuania**

Product category **Toys**

Type **Consumer**

Product ** **

Brand **Unknown**

Product description **Four squeezable, squeaky toys in the form of Teletubies.Type/number of model: 8810A.**

Risk type **Choking**

Risk description **The product presents a risk of choking because during tension test squeak mechanism which fits the small parts cylinder detached from the toy. The product does not comply with the Toys Directive and the relevant European standard EN 71-1.**

Country of origin **People's Republic of China**

Measures ordered by public authorities **Other : Sales ban and withdrawal from the market ordered by the authority.
Other**

Alert number **[0329/06](#)**



| | |
|--|---|
| Notifying country | Lithuania |
| Product category | Toys |
| Type | Consumer |
| Product | &nbsp; |
| Brand | Unknown |
| Product description | Squeezable, squeaky toy duck "FUNNY TOYS"Type/number of model: YLS-9807. |
| Risk type | Choking |
| Risk description | The product presents a risk of choking because during tension test squeak mechanism which fits the small parts cylinder detached from the toy. The product does not comply with the Toys Directive and the relevant European standard EN 71-1. |
| Country of origin | People's Republic of China |
| Measures ordered by public authorities | Other : Sales ban and withdrawal from the market ordered by the authority. Other |